



1

Unpack **Cradle** or Cables from Box. Connect Power and USB Cable to PC



- Windows 10®: Wait until Windows 10 Starts Driver and Windows Mobile Device Center Installation after connecting



2

Insert CD or Portable Drive



3

- Run Setup.exe
- Does the following message appear?
".Net 3.5 must be installed"
Then Run \DotNetFX35 from Drive
- Continue with Setup ...

4

Crystal Reports® Installation Starts
Follow Prompts to Complete...

5

Windows Mobile Device Center®
Installation Starts (if not installed
already), follow prompts to complete

Turn On, Connect Device



6

Finish and Close Setup
Congratulations! Installation is Complete
Review Documents and Training